

CERTIFICATE OF INSPECTION

WE HEREBY CERTIFY THAT THE FIRE EXTINGUISHING APPLIANCES AS SET OUT BELOW HAVE BEEN SERVICED IN ACCORDANCE WITH BS5306-PT3:2009 AND FUTURE AMENDMENTS AND INSTALLATION TO BS5306-PT8:2012



REGISTRATION No: 3818395

CERTIFICATE NO:

48365

NEW CUSTOMER	<input type="checkbox"/>
NEW INSTALLATION	<input type="checkbox"/>
ANNUAL SERVICE	<input checked="" type="checkbox"/>
CALL OUT	<input type="checkbox"/>
SITE EQUIPMENT	<input type="checkbox"/>



PURCHASE O.NO: _____

LOCATION ADDRESS	CHEW ESTON VILLAGE HALL CAUDECOTT ROAD CHEWESTON NORTHANTS. POSTCODE NN9 6AT.
MAIN CONTACT	ADRIAN DALE
MAINTENANCE CONTACT	
TEL No.	MOBILE No 07850 57007

ENGINEERS RECOMMENDATIONS & COMMENTS/
INVOICE ADDRESS (if different)

QUOTE No

APPLIANCE	SIZE	TOTAL INSPECTED	INITIAL SERVICE COMMISSION	BASIC SERVICE	EXTENDED SERVICE	OVERHAUL	REFILL	RECHARGE	ADVISE REPLACEMENT	SUPPLY NEW	DISPOSAL	WALL MOUNTED	SERVICE EXCHANGE
WATER	6ltr	2		1	1								
WATER + ADDITIVE													
WATER + ADDITIVE													
FOAM	6ltr	1		1									
FOAM													
POWDER													
POWDER													
POWDER													
POWDER													
HOSE REELS													
CO2	2kg	3		3									
CO2													
WET CHEMICAL													
FIRE BLANKETS	1x1	1		1									

SIGNS ID FINAL EXIT DIRECTIONAL FIRE ACTION CALL POINT PUSHBAR TO OPEN FIRE EXIT KEEP CLEAR HIGH LEVEL

PARTS USED	SECURITY SEALS	7	OK PIN		CO2 PIN		O RING HOSE AND HORN	6	CO2 HOSE & HORN HEAD ASSEMBLY	
	CO2 HORN		HEAD CAP PIN		FPS PIN		O RING HCAP SMALL	1	NOZZLE	
	55GM CARTRIDGE		TG RED PIN		SMALL PIN		O RING HCAP LARGE		DIP TUBE	
	75GM CARTRIDGE		GLORIA PIN		O RING HOSE		HOSE ASSEMBLY	1	FROST FREE HORN	
	95GM CARTRIDGE		CHUBB PIN		O RING HORN		GAUGE			

ADDITIONAL SERVICE DETAILS

SITE VISIT AND SERVICE 7 UNITS
EQT PARTS AS ABOVE

DATE OF INSPECTION

SERVICE ENGINEER

CUSTOMER SIGNATURE

28/2/2023

ANDY STEARNS

[Signature]

MONTHLY INSPECTION BY THE RESPONSIBLE PERSON

The owner occupier needs to establish the general condition and availability of the extinguishers. Extinguisher inspections should include:

- Is it located in the designated place?
- Is it unobstructed and visible?
- Are the operating instructions clean, legible and facing out?
- Has it been operated and no damage sustained, or parts missing?
- The reading of any gauge should be within operational safety limits
- Are the limits or tamper indicators broken or missing?

THE GERALD LLOYD BUILDING
16 ORLINGBURY ROAD
LITTLE HARROWDEN
NORTHAMPTONSHIRE
NN9 5BH
TEL: 01933 677125
EMAIL: sales@isefireproducts.co.uk
www.isefireproducts.co.uk